



# Powder Coated Metal

## Regular Cleaning

Powder coated metal is durable and does not require any particular type of maintenance. Simply wipe with a soft cloth wrung in hot water, possibly containing a mild cleaning agent if necessary. Wipe the surface with a dry cloth, immediately after.

Make sure to always wipe the metal frame after washing the floor to avoid stains.

## Stain Removal

Dust, dirt and grease: Wipe clean with a soft cloth firmly wrung in hot water containing a mild cleaning agent.

Marks from shoe polish/rubber: Wipe clean with a soft cloth firmly wrung in hot water containing a mild cleaning agent. You may use methylated spirits or cleaner's naphtha on tougher stains.

**Δ Do not use any solvents or cleaning agents with sanding qualities, as these will permanently damage the surface.**